

## *Software Version 13.43.7*

### INTERNATIONAL SYMPTOM/CONDITION:

Turn by Turn navigation in the cluster set to ON by default\*\*.

Postal code navigation search for European markets only\*\*.

Transfer button does not pick-up and transfer incoming call\*\*.

Voice Recognition (VR) says 'cancel' when starting (App) applications\*\*.

Some Russian letters are caps when they should be lower-case\*\*.

Touch screen locks up in navigation, when Russian is selected\*\*.

Address search available when the vehicle is moving (European market)\*\*.

VR messages in Spanish talks to fast\*\*.

Recognition enhancement for Russian VR\*\*.

Hands free audio too low for non-amp vehicle (KL)\*\*. • Intermittently "Registration expired" pop-up appears on display screen\*\*.

Arabic language for navigation only, not the keyboard (RJ3 RJ4 radio only)\*\*.

Incorrect time to destination, when ignition is cycled\*\*.

Volume adjustment for navigation prompts, for phone call\*\*.

Incorrect rear to center fade displayed at start up\*\*.

Translation enhancements for French German and Spanish\*\*.

Right arrow doesn't work for advancing through preset\*\*.

Map zoom level reduced\*\*.

Park sense audio tone stuck on\*\*.

While in rear media the browser knob is disabled\*\*.  
Varies POI not available for navigation\*\*.  
Postal code search not working in some markets\*\*.  
Horn sounds when locked is missing in the settings menu\*\*.  
Mute button out of sync with mute in the hands free phone\*\*.  
Enhancements my for hands free phone locking up\*\*.  
Enhancements to quick search\*\*.  
Backup camera active guide lines are missing.  
-3- 08-049-13 REV. F  
Sound horn when locking, missing.  
Erratic Interior ambient lamp menu being displayed.  
Remove auto entry/exit from menu.  
Remove hill start assist from menu, when not available.  
Russian keyboard enhancements.  
Polish text update.  
Black screen intermittently displayed.  
VR teleprompter translations.  
Splash screen not showing after remote unlock.  
Translation enhancement for Spanish, German, French and Russian.  
Russian letters are in caps when they should be in lower case.  
Parkview/Parksense translations in Russian.  
Nav locks up when Russian is selected.  
VR Spanish language talks too fast when giving instructions.  
Arabic language added to some features (RJ3 RJ4 radios only).  
VR enhancements for Russian.  
Route guiding enhancements.  
HVAC display enhancements.